

876 Otter Creek Road Oregon, Ohio 43616-3518 Phone: (419) 698-3500 Fax (419) 698-8663

Website: www.envirosafeservices.com

November 7, 2022

**VIA ELECTRONIC MAIL** 

Mr. Michael Terpinski Ohio EPA, NWDO, DERR 347 North Dunbridge Road Bowling Green, OH 43402

Re: Envirosafe Services of Ohio, Inc.

**EPA Identification Number: OHD 045 243 706** 

**October 2022 Progress Report** 

Dear Mr. Terpinski:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), Envirosafe Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning October 1, 2022 and ending October 31, 2022.

### **Corrective Measures Implementation ("CMI"):**

#### **Project Activities:**

During this reporting period, CMI activities included the following:

- 1. Submission as a permit modification of the Corrective Measures Completion of Work (CMCW) Report for the SWMU 6 Fence Line Remediation project on October 20, 2022;
- 2. Drafting of the SWMU 7 roadway evaluation in the area of boring S7-202;
- 3. Leachate system maintenance included:
  - Inspection of piezometers and recovery wells on SWMUs 5, 6, and 7:
    - Recorded liquid level at each location with a control panel;
    - Verified functionality of all pumps without a control panel;
    - All pumps with a control panel were observed to be below their respective low points with the exception of: RW-11, DPW-18, 19, 22, NRP-24, 25, 26, 27, 28, 29, 30, 31, 33, 34, and 35;
  - RW-1: Observed to have a foamy discharge;
  - NRP-32: Repaired leaking airline;
  - T-20S: Replaced protective casing lid;
  - SWMU 5 Compressor: Drained moisture from controller; and

- SWMU 6 Compressor: Emptied buckets, compressor attic fan was observed to be functioning as designed;
- 4. Solar Sipper inspected and found to be operating as designed, evaluated and repaired low power issue (electrical connection); and

## Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

# Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

### Projected Work:

During the next reporting period it is anticipated that the following activities will occur:

- 1. Submission of the SWMU 7 roadway evaluation in the area of boring S7-202;
- 2. Development of an O&M Plan for the newly installed SWMU 8 extraction wells and gas vents; and
- 3. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact Stephen DeLussa at (215) 659-2001 ext. 15.

Sincerely

Douglas E. Roberts

President

ec:

Gary Deutschman, Ohio EPA-NWDO, DERR Stephen DeLussa, Envirosource Technologies, Inc. Michael Momenee, The Mannik & Smith Group Dawn Pleiman, Ohio EPA-NWDO, DERR Mark Nielsen, Ramboll