

June 10, 2025

**VIA ELECTRONIC MAIL**

Mr. Michael Terpinski  
Ohio EPA, NWDO, DERR  
347 North Dunbridge Road  
Bowling Green, OH 43402

**Re:      Envirosafe Services of Ohio, Inc.  
         EPA Identification Number: OHD 045 243 706  
         May 2025 Progress Report**

Dear Mr. Terpinski:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), Envirosafe Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning May 1, 2025 and ending May 31, 2025.

**Corrective Measures Implementation ("CMI"):**

**Project Activities:**

During this reporting period, CMI activities included the following:

1. Leachate system maintenance included:
  - Inspection of piezometers and recovery wells on SWMUs 5, 6, and 7:
    - Recorded liquid level at each location with a control panel;
    - Verified functionality of all pumps without a control panel;
  - RW-1:                Not discharging - cleaned pump screen and replaced broken hose clamps - began pumping with significant discharge;
  - RW-3:                Displaying negative level – pump and transducer stuck in well – maintenance scheduled;
  - PZ-13:                Pump stuck in well and inoperable – assessing replacement;
  - DPW-19:             Displaying negative level – ultimately replaced transducer;
  - DPW-22:             Transducer unresponsive – replacement scheduled;
  - NRP-26:             Above hi point – replaced pump and added surfactants to manage leachate viscosity – pump starter not engaged - replacement scheduled;
  - NRP-29:             Above hi point – replacement scheduled;
  - NRP-32:             Cleaned pump screen and repaired hole in airline - began pumping;
  - NRP-33:             Display dim - replaced with used display from RW-6;
  - SWMU 6 Compressor: emptied condensation bucket – compressor and attic fan observed to be functioning as designed;

Mr. Michael Terpinski

June 10, 2025

Page 2

2. NAPL Recovery System – NAPL levels observed as skim to not present - absorbent socks observed with available capacity.

**Summary of All CMI-Related Contacts with the Public:**

ESOI has not had any related contacts with the public during this reporting period.

**Summary of Potential or Encountered Problems and Rectification Actions:**

There is nothing to report in association with this topic for this reporting period.

**Projected Work:**

During the next reporting period it is anticipated that the following activities will occur:

1. RW-1 – replace test valve;
2. RW-3 – free stuck pump and repair/replacement of transducer – not urgent or impacting TLL;
3. PZ-13 – Replacement of damaged riser, discharge line and pump if needed – active as piezometer;
4. DPW-22 – Replacement of transducer – not urgent or impacting TLL;
5. NRP-26 – Replacement of pump starter;
6. NRP-29 – Replacement of pump starter; and
7. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact me at (224) 723-8215.

Sincerely,



Stephen J. DeLussa

Corporate Director – TSDF Compliance

ec: Franklin Ireland, ESOI  
Audrey Jones, ESOI  
Dawn Pleiman, Ohio EPA-NWDO, DERR  
Michael Momenee, The Mannik & Smith Group

Kristofer Mann, ESOI  
Gary Deutschman, Ohio EPA-NWDO, DERR  
Mark Nielsen, BBJ Group