

876 Otter Creek Road Oregon, Ohio 43616-3518 Phone: (419) 698-3500 Fax (419) 698-8663

Website: www.envirosafeservices.com

June 10, 2024

VIA ELECTRONIC MAIL

Mr. Michael Terpinski Ohio EPA, NWDO, DERR 347 North Dunbridge Road Bowling Green, OH 43402

Re: Envirosafe Services of Ohio, Inc.

EPA Identification Number: OHD 045 243 706

May 2024 Progress Report

Dear Mr. Terpinski:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), Envirosafe Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning May 1, 2024 and ending May 31, 2024.

Corrective Measures Implementation ("CMI"):

Project Activities:

During this reporting period, CMI activities included the following:

- 1. Leachate system maintenance included:
 - Inspection of piezometers and recovery wells on SWMUs 5, 6, and 7:
 - Recorded liquid level at each location with a control panel;
 - Verified functionality of all pumps without a control panel;
 - PZ-13: Repaired holes in airline;
 - PZ-15: This well is a piezometer and a pump was installed as an extra pumping well but not included or required by the OMPM Plan. Since the pump has become wedged in the well and unable to be removed, it will no longer be pumped;
 - NRP-27: Clean actuator connections to prevent sticking;
 - NPR-29: Replacement pump on order manufacturer is behind on production alternatives being evaluated;
 - NRP-30: Cleared ant colony from control panel and cleaned actuator connections;
 - NRP-32: Repaired holes in airline;
 - SWMU 6: Repaired a short within the wires leading to the SWMU 6 storage tank;
 - SWMU 5 Compressor: Drained moisture from controller;
 - SWMU 6 Compressor: Emptied buckets, compressor attic fan was observed to be functioning as designed; and

2. Solar Sipper – Remains off - socks are performing well and NAPL production has slowed – all well LNAPL levels are skim to not present.

Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

Projected Work:

During the next reporting period it is anticipated that the following activities will occur:

- 1. Replace NRP-29 pump and possibly transducer;
- 2. Assess ongoing need for Solar Sipper vs absorbent socks at SWMU 5 NAPL wells; and
- 3. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact me at (224) 723-8215.

Sincerely,

Stephen J. DeLussa

Corporate Director – TSDF Compliance

Kristofer Mann, ESOI ec:

Gary Deutschman, Ohio EPA-NWDO, DERR

Mark Nielsen, BBJ Group

Dawn Pleiman, Ohio EPA-NWDO, DERR Michael Momenee, The Mannik & Smith Group