

July 10, 2026

VIA ELECTRONIC MAIL

Mr. Michael Terpinski
Ohio EPA, NWDO, DERR
347 North Dunbridge Road
Bowling Green, OH 43402

**Re: Envirosafe Services of Ohio, Inc.
 EPA Identification Number: OHD 045 243 706
 June 2026 Progress Report**

Dear Mr. Terpinski:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), Envirosafe Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning June 1, 2026 and ending June 30, 2026.

Corrective Measures Implementation ("CMI"):

Project Activities:

During this reporting period, CMI activities included the following:

1. Leachate system maintenance included:
 - Inspection of piezometers and recovery wells on SWMUs 5, 6, and 7:
 - Recorded liquid level at each location with a control panel;
 - Verified functionality of all pumps without a control panel;
 - RW-3 – Transducer wires found separated from control panel – reconnected wires and reset breaker – unkinked discharge line – observed to be level within interval;
 - DPW-18 – Replaced loose fuse – replaced relay in control panel – in process of electrical evaluation to determine if pump started is in need of replacement;
 - NRP-25 – Transducer wires found damaged – removed damaged wires and spliced together – replaced transducer - level found to be within interval;
 - NRP-26 – New pump starter installed – cleaned well and worked pump up and down – continued to observe no discharge – leak observed in force main – in process of sourcing parts for repair;
 - NRP-28 – Reset tripped breaker – level observed to be within interval;
 - NRP-27 – Displaying slightly negative level – to evaluate further next visit;
 - NRP-29 – Observed above hi point – pump starter replacement scheduled;
 - NRP-30 – Transducer wires found separated from control panel – reconnected wires and removed and spliced damaged section of line – level observed to be within interval;
 - SWMU-6 compressor: Emptied condensation bucket - Compressor attic fan observed to be functioning as designed;

Mr. Michael Terpinski

July 10, 2026

Page 2

2. NAPL Recovery System – NAPL levels observed as skim to not present, absorbent socks observed to have available capacity.

Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

Projected Work:

During the next reporting period it is anticipated that the following activities will occur:

1. Change oil in SWMU-6 compressor;
2. DPW-18 – Evaluate electric issues and determine if pump or pump starter replacement is required;
3. NRP-25 – Evaluate electric issues and determine if pump replacement is required;
4. NRP-26 – Thoroughly clean pump and attempt dilution and loosening of viscous leachate to enable pumping, repair force main leak;
5. NRP-27 – Evaluate electric issues to determine cause of negative level reading;
6. NRP-29 – Replacement of pump starter;
7. PZ-13 – Replacement of damaged riser, discharge line and pump if needed – active as piezometer;
8. Continue maintenance of leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact Audrey Jones at (419) 343-6187.

Sincerely,



Franklin Ireland
General Manager

ec: Franklin Ireland, ESOI
Audrey Jones, ESOI
Dawn Pleiman, Ohio EPA-NWDO, DERR
Michael Momenee, The Mannik & Smith Group

Stephen DeLussa, CC
Gary Deutschman, Ohio EPA-NWDO, DERR
Mark Nielsen, BBJ Group